

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 28


Township: 8 North

Range: 1 West

Corner ID: Per I-19

Monument Description & Remarks: Found old rusty Iron Pipe, 0.3' diameter, at West 1/4 corner of section. Iron pipe was painted orange and marked with old orange and pink flagging. Survey lathe stake at corner read "SW corner, NW 1/4, Section 28." County Surveyor note: new monument needed.

References on file in the County Surveyor's Office: Survey by Ben Bledsoe, R.L.S. No. S0559, recorded in Book 4, Page 488 in the Recorder's Office.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 27th day of January, 1998.

Kevin P. Enright

Administered by: Surveyor Review Board

